

SECRET

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO :

FROM :

ACTION:

INFO :

IN: 91947

ops, u D

TO

INFO

CITE

SECRET 260819Z CITE [REDACTED] 1381

25X1A

PRIORITY [REDACTED]

25X1A

25X1A

C216C/260230Z/385

SYSTEM 6

1. 26/D/1011/65/37/34/1001/21
2. SPOT CHECK NEAR END OF MISSION INDICATED THAT SYSTEM FUNCTIONED PROPERLY.

SYSTEM 9B

1. 106
2. NO ACTIVITY --SELF TESTED OK.

SYSTEM 12B

1. 14/143/143
2. NO ACTIVITY --SELF TEST OK.

SYSTEM 13C

1. B-602
2. REPEAT LIGHT FROM 0355 TO 0403Z. OVERHEAT LIGHT CAME ON AT 0500Z DUE TO PRESSURIZATION PROBLEM AND STAYED ON FOR REST

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

S E C R E T

PAGE-2 [REDACTED] 1381

IN: 91947

25X1A

OF FLIGHT. SELF TESTED OK.

OSCAR SIERRA

1. 3

2. NO ACTIVITY--SELF TESTED OK.

[REDACTED] SATISFACTORY

25X1A

RADIO AND NAVAIDS SATISFACTORY

UMY-20 C791--100 PERCENT

S E C R E T TOR: 26/0915Z NOV 66

S E C R E T